

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,611,169 B2  
APPLICATION NO. : 10/552791  
DATED : November 3, 2009  
INVENTOR(S) : Springmann et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Column 7, line 25 (Line 20 of Claim 1) after the word "block" please insert: --cover--.


In Column 8, line 15 (Line 1 of Claim 11) please change "whereby" to: --wherein--.

In Column 8, line 37 (Line 14 of Claim 14) please delete: "wherein a plug-in receptacle for receiving a plug-in pipe." (second occurrence).

In Column 8, line 42 (Line 19 of Claim 14) after the word "cover", please delete: "(9)".

Signed and Sealed this

Twenty-seventh Day of April, 2010



David J. Kappos  
Director of the United States Patent and Trademark Office